

Oil Field Environmental Incident Summary

Incident: 20150306091524 **Date/Time of Notice:** 03/06/2015 09:15
Responsible Party: XTO ENERGY INC.
Well Operator: XTO ENERGY INC.
Well Name: JACQUELINE 11X-1B
Field Name: MIDWAY **Well File #:** 27181
Date Incident: 3/5/2015 **Time Incident:** 11:00 **Facility ID Number:**
County: WILLIAMS **Twp:** 157 **Rng:** 96 **Sec:** 1 **Qtr:**
Location Description: Oil spray misted north off location onto landowner property

Submitted By: JORDAN WOLF **Received By:**

Contact Person: KAYLAN DIRKX
P.O Box 6506
325 22ND AVE E
WILLISTON, ND 58801

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Other

Release Contained in Dike No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Gallons				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Minor impacts- fine mist on top of snow

Areal Extent:

Approximately 10 gallons oil misted to the north approximately 350'

Potential Environmental Impacts:

Minor impacts- fine mist on top of snow

Action Taken or Planned:

Waiting on return call from landowner before continuing cleanup.

Wastes Disposal Location: Justin SWD

Agencies Involved:

Updates

Date: 3/6/2015 **Status:** Reviewed; Followup Required **Staff:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 3/19/2015 **Status:** Inspected **Staff:** Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Report says misting to the north. Strip of cropland to the north has been stripped of vegetation.